

Fig. 2. Detection of  $\beta$ -1,3-glucanase in the inoculation fluid recovered from lily leaves.




Fig. 3. The 2D-electrophoresis analysis of the inoculation fluid of *B. elliptica* recovered from lily leaves.




Fig. 6. Comparison of the infection of lily leaves and flowers by *B. elliptica*.




Fig. 1. shows the protein patterns of the inoculation fluids of *Botrytis* spp. recovered from lily leaves and flowers.